



Questions about Arsenic?

01

Testing in 2017

MLGW results for 2017 Arsenic (As) and Lead (Pb) data from the operating production wells at the Davis Well Field: There were trace amounts of Pb in Davis wells #422 and #424. Both wells were retested about 2 weeks later and Pb was determined to be BDL*.

02

Independent Lab Results

Since the initial testing of the Davis Well Field, Davis well #409 was tested later in August 2017; Arsenic and Lead were both BDL*. All samples were analyzed by ESC Lab Sciences (currently PACE Analytical).

03

Testing in 2020

In July 2020, Davis Well #402 was tested; As and Pb were both BDL*.

04

Water Quality Report

View the MLGW Water Quality reports from the past decade at: mlgw.com/about/waterqualityreport

*BDL-Below detection level